

Nº 5027

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-5-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM "Y" at Sta. 1+08 9'Deep

HOUSE NO. 332

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 11' 7"


WAS LATERAL AT CURB? No.

WAS ATTACHED TO MAIN Yes.

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Line originally run in
and insp on 5-25-46
House now being started



SIGNED R. F. Smythe
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 9/9/47

REMARKS: _____

Nº 5027

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/29 1947
 RECEIVED OF Chas Keuper FEE OF \$ 2.00
 FOR WHICH PERMISSION IS GRANTED same
 TO TAP San SEWER, ON THE N SIDE
 OF Belaware Ave TYPE OF STREET dirt
 THE PREMISES BEING LOT NO. 10584, HOUSE NO. 332

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H. Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.