

N^o 5037

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

1
18

DATE INSPECTED 7-22-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 333

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 58 8' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Astom

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

121 ST. S.E.



SIGNED

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7/24/47

REMARKS: _____

Nº 5037

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

9/20 1947

RECEIVED OF

Harvey Aston

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Doyle Lawrence

TO TAP

Sanitary

SEWER, ON THE

west

SIDE

OF

1st St. N.E.

AVE.
ST.

TYPE OF STREET

parade

THE PREMISES BEING LOT No.

357

HOUSE No.

333

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harvey Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.