Nº 5043

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FR		
HOUSE NO. 649	DISTANCE FROM FIRST MANH DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? Ye WAS ATTACHED TO MAIN YE SHOW BY DIAGRAM RELATION	NAME OF CONTRACTOR	Diana Ing served	
	ung. St. S.E.	2 6'4091	
grammer in institutional titude dies finales.	resembled an across philips (company)	16 / Tidey	16
SIGNED JOHN INSPECTOR	FILED AT	T ENGINEER'S OFFICE	4-48 336
DEMARKS.		•	

Nº 5043

PERMIT TO TAP SEWER

	10/0 -
MAS MAS	ssillon, Ohio, 1947
$G : V \times X \to X$	2 22
RECEIVED OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED THE	alin Baratist de 1
FOR WHICH PERMISSION IS GRANTED	
TO TAP Sanctary SEWER, ON	THE SIDE
N . 11/6	
OF TYPE OF	STREET
0256	House No. 649
THE PREMISES BEING LOT NO.	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	. 2323. DULY PASSED BY THE CITY COUNCIL, AND

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.