FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-11-47	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM						
size of PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH The stream of the stream						
WAS LATERAL AT CURB? Yes							
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR PIANA						
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.							
Main Ave.	· W.						
∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴∴<	2 Joseph						
	17 4 16						
SIGNED Jehn Elinspector for city	FILED AT ENGINEER'S OFFICE						
REMARKS.							

Nº 5046

N° 5046

PERMIT TO TAP SEWER

	er e	ÿ	Massil	LON, OHIO,	10/11	1942_
Rec	CEIVED OF	aren	هر مراس	and	FEE OF \$2	00
FOR WHI	CH PERMISSION IS G	RANTED	Rans			
TO TAP		by	SEWER, ON THE	רל .		SIDE
of	Muen	71_	AVE TYPE OF ST	reet <i>Oa</i>	ue S.	
THE PREM	lises being Lot No.		25		240	
					1 The second second	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

 \sim 0 ℓ

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.