

Nº 5050

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-21-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

63. 7' deep

HOUSE NO. 904

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Reinley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

7TH ST. S.W.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/16/47

REMARKS:

Connected to new line. took off old line.

Nº 5050

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/20 1947
RECEIVED OF Raymond Remley FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED J. A. Smith
TO TAP Spany SEWER, ON THE E SIDE
(Overlook sewer)
OF 7th AVE., TYPE OF STREET Alled
THE PREMISES BEING LOT NO. 3343 HOUSE NO. 904

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.