1	24	FOL
No	5054	

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8 22 - 47	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		S' deep	
HOUSE NO				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	· March Allen		
WAS LATERAL AT CURB?				
WAS ATTACHED TO MAIN		Bemley.		
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING	SERVED.		
32 NO ST N.	W			•
<u> </u>	general more dissipat, supplies and 2000 FM-200 PM		, ,	
			deef	
			•	
				MIT
		17	280	
		•	ed.in.	
SIGNED The state of the state o	FILED AT EN	NGINEER'S OFFICE	1117147	Section and a second
INSPECTOR FOR CIT	<b>T</b>			
REMARKS:				

## Nº 5054

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		*1	143	
	The second secon	MASSILLON, OH	10,	194/
RECEIV	ED OF LAHAM	nd Tems	Lid fee of	*
FOR WHICH I	DEDMISSION AS GRANTED	Lune D. F.	Tichter	
TO TAP	San	SEWER, ON THE	1	SIDE
of 32	かん カル	AVE., TYPE OF STREET	des 4	3104
THE PREMISES	S BEING LOT NO. 557	75, House	e No. 717	
a la	DONE IN ACCORDANCE WITH		LY PASSED BY THE CIT	Y COUNCIL, AND
	IE DEPARTMENT OF PUBLIC SI	ERVICE.		
Name of Co	NTRACTOR Tan	ley		
	Art 6	/		

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.