

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB?_____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

32 ND, 57. N.W.



SIGNED

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/17/41

REMARKS:

Nº 5055

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/3 1947

RECEIVED OF R. Ramsey FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED David + Eleanor Beadle

TO TAP San SEWER, ON THE E SIDE

OF 32nd St. AVE., TYPE OF STREET St.

THE PREMISES BEING LOT NO. L 212 HOUSE NO. 700

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ramsey

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.