

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

14
28

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

60. 8' deep

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6


WAS LATERAL AT CURB?_____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

32ND ST. N. W.



SIGNED

John E. Hunter
INSPECTOR FOR CITY

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

11/17/97

REMARKS:

Nº 5057

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/3

1944

RECEIVED OF P. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Harvey Balin

TO TAP San

SEWER, ON THE E

SIDE

OF 325 E 7th

AVE.,
ST.,

TYPE OF STREET Dist

THE PREMISES BEING LOT NO. 15213

HOUSE NO. 706

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR P. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.