V9 5058

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-24-47	if so how and location from first manhole down stream	8' deef,
HOUSE NO. 742	_	
12	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
SIZE OF PIPE USED	CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	- pro	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.	
32 NO ST. N	W	6
		1/ Tideel
		40/
E-manuscript de la company de	Andrews and the second	, 71
	MH. 26, 3	/8!
SIGNED John Sho	FILED AT ENGINEER'S OFFICE	1/17/47
INSPECTOR FOR C	İİTY	
REMARKS:		. F

N? 5058

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,		194
Rusmond	Remby	FEE OF \$	00
RECEIVED OF	A neme	<u>ti</u>	
FOR WHICH PERMISSION IS GRANTED	G.		SIDE
23 1 3	R, ON THE	· 1	
OF AVE. TY	PE OF STREET	742	
THE PREMISES BEING LOT NO.	HOUSE NO.	SED BY THE CITY CO	UNCIL. AND
WILL TO BE BONE IN ACCORDANCE WITH ORDINANO	CE NO. 2323. DULT PAS	350 D. THE OTT. OF	

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.