

Nº 5068

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

9/3

DATE INSPECTED 11-7-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 119' 9' deep

HOUSE NO. 3211

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Bernley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way. N.W.



SIGNED John Ehrmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 11/17/47

REMARKS: _____

Nº 5068

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/13 1947

RECEIVED OF P. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Charles Robertson

TO TAP San

SEWER, ON THE S

SIDE

OF Lincoln Way NW

AVE.
ST.

TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 103223

HOUSE NO. 3241

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR P. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.