

Nº 5071

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-17-47 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1132 1527


SIZE OF PIPE USED 6" up DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 194- 5' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3RD ST. S.E.
N. →



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

up stream. 12/1/47

REMARKS: _____

Nº 5071

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/18 1947

RECEIVED OF A. J. Deane

FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED Barbara K. Deane

TO TAP San

SEWER, ON THE 76.

SIDE

OF 3rd & E.

AVE.,
ST.

TYPE OF STREET Alley

THE PREMISES BEING LOT NO. 5340

HOUSE NO. 1132

1527

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Deane

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.