Nº 5079

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1-4-48	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED 4	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Yes	
WAS ATTACHED TO MAIN	
SHOW BY DIAGRAM RELATION OF LATE	
16 TH ST,	N = 1
	A STATE OF THE STA
	man to the second of the secon
	170
	The state of the s
SIGNED Gara Chroni	FILED AT ENGINEER'S OFFICE 3/6/1/4/
INSPECTOR FOR CITY	
REMARKS:	

Nº 5079

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		, Massillon, Ohio,_	1/2 FEE OF \$2	1948
FOR \	VHICH PERMISSION IS GRANTED	Vann		
TO TA	P. SEWE	R, ON THE	last	SIDE
of	110 1128		pared	· .
THE P	REMISES BEING LOT NO. 586/	, House No	740	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323. DULY PASSED BY THE CITY COUNCIL, AND

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. Jana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.