

5-30

N^o 5090

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-6-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 1619SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH160' 6 1/2' DeepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN -


NAME OF CONTRACTOR

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Dist. from curb
to foundation 36'
End of existing
lateral was 4' out
in street.

↓
N

SIGNED R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: Total of 40' pipe laid3-8-48
H

Nº 5090

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

1948

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

SIDE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.