Nº 5092

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 4-1-48 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | |
|--|--|--|
| HOUSE NO | | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 70' | 8. deep |
| WAS LATERAL AT CURB? | dan. | |
| WAS ATTACHED TO MAIN Yes | NAME OF CONTRACTOR REPUED | ey. |
| SHOW BY DIAGRAM RELATION OF LATE | ERAL TO WALL OF BUILDING SERVED. | |
| 15 TH ST. 1 | V W | 9 |
| 1 A | 64 | |
| <u> </u> | <i>N</i> . | الم |
| Approximation of the state of t | per control of the period of the control of the con | 23 |
| | | grdeef |
| | , and the state of | inaurum saanaa saasaa ka yoka aadamaa saasaa saasaa saasaa saasaa saasaa ka aa a |
| SIGNED John Thin | FILED AT ENGINEER'S O | FFICE 4/4/4/4 |
| INSPECTOR FOR CITY | • | |
| REMARKS: | | |

Nº 5092

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| 3/16 | 194 |
|--|-------|
| MASSILLON, OHIO, FEE | |
| RECEIVED OF | |
| TO TAPSEWER, ON THE | SIDE |
| OF | |
| THE PREMISES BEING LOT NO. 8640, House No. 34. | · |

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND

AME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.