Nº 5095

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-20-48	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. New Horse		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7. Leep
WAS LATERAL AT CURB? 1 6 5	A from	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	*7
SHOW BY DIAGRAM RELATION OF LATE		Solid Survey
Tremont, A	ve. S.W.	4
		18/ 6/20
2	30.	
1	6	
SIGNED John Ehm	FILED AT ENGINEER'S OF	FICE A CONTRACTOR
INSPECTOR FOR CITY	,	
REMARKS:		

N? 5095

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohio,	3/18	194
RECEIVED OF H. aston		FEE OF \$	<u> </u>
FOR WHICH PERMISSION IS GRANTED . K	enney	south	
TO TAP Sanetary SEWER	R, ON THE	ment	SIDE
of from the AVE. TYP	E OF STREET	farea	
THE PREMISES BEING LOT NO. 268	House No		

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

IAME OF CONTRACTOR & destun

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.