Nº 5101

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4 3 48	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		· · · · · · · · · · · · · · · · · · ·
HOUSE NO. 1846			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	143.	5'deep
WAS LATERAL AT CURB? YES			•
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Boger.	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING	SERVED.	
Jefferson k	IVE. N.E.		6
*	1 · · · · · · · · · · · · · · · · · · ·	, ,	1 6: doch
Z		76	
	118 3	244	
SIGNED John Eline INSPECTOR FOR CITY	G 143	GINEER'S OFFICE	
INSPECTOR FOR CITY	•		
REMARKS:			

Nº 5101

NAME OF CONTRACTO

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillo	и, Оніо,	130	194
RECEIVED OF	<u> </u>		FEE OF \$2	\
OR WHICH PERMISSION IS GRANTED		The second second	<i>and</i>	· · · · · · · · · · · · · · · · · · ·
O TAP SEWEI	R, ON THE			SIDE
FLAND DE TY	PE OF STREE	ет	11	
HE PREMISES BEING LOT NO. 8/05	, I	House No	1846	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	- No 222	9 mm v n.ecr		COUNCIL AND

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND

/6//4/

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.