Nº 5102

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-1-48	IF SO HOW AND LOCATION FROM 126	<u></u>
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	·
WAS LATERAL AT CURB?	NAME OF CONTRACTOR ASTON	
WAS ATTACHED TO MAIN		
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	Customaria de la compansa de la comp
Indiana	Ave, NE	
		4/1568
*		
	0 120	/18
SIGNED John Thom	filed at engineer's office_	4117122
INSPECTOR FOR CIT	Y	planting property and the solution of the solu
REMARKS:		

Nº 5102

PERMIT TO TAP SEWER

	Massillon, Oh	10. 4/1 1948
RECEIVED OF	Kleyen	FEE OF \$2
FOR WHICH PERMISSION IS GRANTED	Harvey asi	tn
TO TAP Sanitar	sewer, on the	gravel SIDE
or Indiana K	AVE TYPE OF STREET	south
THE PREMISES BEING LOT NO.	0704 Housi	ENO 307 251

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR Farvey Uston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.