

14-20

Nº 5106

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-26-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 323

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE up
~~DOWN~~ STREAM TO DITCH AT 39'
CURB LINE AND DEPTH 7 1/2' Deep.


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

↓
N



SIGNED R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 5-26-48

REMARKS: _____

Nº 5106

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/1 1918

RECEIVED OF E. P. Kemper

FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED H. Astor

TO TAP sanitary

SEWER, ON THE South

SIDE

OF Indiana N.E.

3rd AVE., TYPE OF STREET gravel

THE PREMISES BEING LOT NO. ~~10707~~ 10748

HOUSE NO. ~~1322~~ 323

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Astor

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.