

Nº 5108

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-3-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 723

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 156



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

12TH ST. S.W.



SIGNED

John E. Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4/12/48

REMARKS: _____

Nº 5108

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/3 1948
RECEIVED OF Harvey Aston FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Frank Rohr
TO TAP sanitary SEWER, ON THE west SIDE
OF 12th St SE AVE., TYPE OF STREET dirt
THE PREMISES BEING LOT NO. 4685, HOUSE NO. 723

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harvey Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.