

Nº 5111

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-7-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1638

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 88' 7' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Coventry Rd. NE

N →



SIGNED

John E. Houser
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4/15/48

REMARKS: _____

Nº 5111

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/6 1948
RECEIVED OF H Aston FEE OF 2.00
FOR WHICH PERMISSION IS GRANTED Gilbert Scott
TO TAP San SEWER, ON THE N. SIDE
OF Conventy Rd NE AVE., TYPE OF STREET dirt
THE PREMISES BEING LOT NO. 8333 HOUSE NO. 1633

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H Aston

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.