Nº 5116

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-3-48	IF SO HOW AND LOCATION FROM
HOUSE NO	FIRST MANHOLE DOWN STREAM
7	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
SIZE OF PIPE USED	CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Remley
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
15t ST. S.	W.
	E J. ICE Mouse.
٨/	2/5
Commence and the second	2/4
	LOWRY. Laneline &
SIGNED Jahr Shin	
INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS: Connected	in M.H.

Nº 5116

NAME OF CONTRACTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASS	SILLON, OHIO, 15	94)
RECEIVED OF	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED	+ Defollers	
		a:==
OF	11 Part 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	SIDE
THE PREMISES BEING LOT NO. 1374		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.	2323. DULY PASSED BY THE CITY COUNCI	L, AND

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.