## Nº 5124

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-15-45 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM
HOUSE NO
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE  CURB LINE AND DEPTH 15. The suffy
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Behaley
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
27 TH ST. S.E.
7'dee/
Zana Alamana and and and and and and and and and
115, 7'deels 6.
SIGNED John Literator FILED AT ENGINEER'S OFFICE 6-28 45
SIGNED FILED AT ENGINEER'S OFFICE
REMARKS:

## Nº 5124

NAME OF CONTRACTOR

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohio,	5/11	194⁄
RECEIVED OF	Decided.	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED	A Carlon Sant		
TO TAPSEWI	ER, ON THE	. 0	SIDE
of 4/7// 1 G AVE TY	PE OF STREET		
THE PREMISES BEING LOT NO.	House No.		<b></b>
WORK TO BE DONE IN ACCORDANCE WITH ORDINAN RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	ICE NO. 2323. DULY PAS	BSED BY THE CITY	COUNCIL, AND

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.