Nº 5127

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-18-4	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 5/8		
HOUSE NO.	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	OURS LINE AND DEPTH 125 -	7. deep
WAS LATERAL AT CURB? / 25	The State Andrew Adjusted the Control of the Contro	·
WAS ATTACHED TO MAIN YCS	NAME OF CONTRACTOR	,
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.	
29TH 5	T. N.W.	12
		1574
		1 des
and the second s	dia wang dipad	1 10
A Commence of the Commence of	The Particular was a contract formal and a contract for the contract formal and a contra	* */
	1	e 17dech
		1812
المناف الأرامين أرام المالية		
1 / 51		
SIGNED INSPECTOR FOR	FILED AT ENGINEER'S OFFICE	6-23-48
INSPECTOR FOR	CHT Services and the services of the	
REMARKS:		

Nº 5127

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	•	5/12	19
Maș	SILLON, OHIO,	110	_194
RECEIVED OF Carlansk	JUm0	ALD FEE OF \$2	09
OR WHICH PERMISSION IS GRANTED	- C Eur	Comake	
And		E	a.p.
O TAPSEWER, ON T	ΠE	A 1/2	SIDE
OF 29th nw AVE. TYPE OF S	STREET	M236	alle
HE PREMISES BEING LOT NO. PA H236	, House No	518	·
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No.	2323. DULY PASS	ED BY THE CITY COU	NCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.			
(Atm)			

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.