


N^o 5138

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-28-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1940SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 298. 7' deepWAS LATERAL AT CURB? YESWAS ATTACHED TO MAIN YESNAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Vermont Ave SE

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-2-48

REMARKS: _____

Nº 5138

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/27 1948

RECEIVED OF H. Astor

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Ralph A. Davis

TO TAP Law. H.

SEWER, ON THE W

SIDE

OF Vermont St.

AVE., TYPE OF STREET clerk
ST.,

THE PREMISES BEING LOT NO. 6191

HOUSE NO. 1940

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Astor

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.