

7-31


N^o 5143

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-11-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 325SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 33' 7'deepWAS LATERAL AT CURB? Yes.WAS ATTACHED TO MAIN Yes.NAME OF CONTRACTOR Remley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

2 family
25th ST. N.W.



SIGNED

John E. Chum
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 6-17-48

REMARKS: _____

Nº 5143

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/5 1941

RECEIVED OF E. Lawson

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Same

TO TAP San

SEWER, ON THE W.

SIDE

OF 25th W

AVE.,
ST.,

TYPE OF STREET Alld

THE PREMISES BEING LOT NO. 8700-8701

HOUSE NO. 325

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.