

Nº 5148

14-20

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-29-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 329

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
TO DITCH AT CURE LINE AND DEPTH 11' 8' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

INDIANA. Ave. N.E.



SIGNED

John E. Hines
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-19-48

REMARKS: _____

Nº 5148

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/12 1948

RECEIVED OF A. Keuper

FEE OF \$ 3.00

FOR WHICH PERMISSION IS GRANTED to use

TO TAP San

SEWER, ON THE S.

SIDE

OF Indiana N.E.

AVE.,
ST.,

TYPE OF STREET dirt

THE PREMISES BEING LOT NO. 10747

HOUSE NO. 329

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Astor

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.