

Nº 5150

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-11-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 104' 5' deep

HOUSE NO. 445


SIZE OF PIPE USED 6
DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR Remley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

12TH ST. N.W.



SIGNED John Ehmer
INSPECTOR FOR CITY

12TH ST. N.W.
FILED AT ENGINEER'S OFFICE 7-20-48

REMARKS: _____

Nº 5150

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/15 1948

RECEIVED OF Rudy Lock

FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED Raymona Remley

TO TAP sanitary

SEWER, ON THE west

SIDE

OF 12th St

AVE.,
ST.,

TYPE OF STREET dirt

THE PREMISES BEING LOT NO. 7907

HOUSE NO. 445

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymona Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.