

8-25

N^o 5152

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED


DATE INSPECTED 6-25-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 818SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH182'8 1/2' DeepWAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-26-48

REMARKS: _____

Nº 5152

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/24 1948

RECEIVED OF

Geo H. Maracich

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

same

TO TAP

San

SEWER, ON THE

E.

SIDE

OF

15th SW

AVE., TYPE OF STREET

Alled

ST.,

THE PREMISES BEING LOT NO.

4787

HOUSE NO.

818

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Rindley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.