## Nº 5157

# FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-2-48	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1412	
/ "	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 69 - 7 DEEP
SIZE OF PIPE USED	CURB LINE AND DEPTH
WAS LATERAL AT CURB? Yes	NAME OF CONTRACTOR ASTON
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
E. Curbline  A mherst Rd. S'Deep &  M. H. Cor. Dexter  Pannerst  Mam Sewer  Signed R. J. Jandu Filed at Engineer's Office 13-12-12-12-12-12-12-12-12-12-12-12-12-12-	
REMARKS:	

#### OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

#### Nº 5157

### PERMIT TO TAP SEWER

Hastin	MASSILLON, OHIO, 190
FOR WHICH PERMISSION IS GRANTED	Actions
10% 104-+ 10 AE	ON THE SIDE
Depter 7 E. THE PREMISES BEING LOT NO. 245 10	680House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323. DULY PASSED BY THE CITY COUNCIL, AND

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HANDEN WATER WATER OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.