

11-13

Nº 5166

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-21-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 132' 5' deep

HOUSE NO. 966

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

9TH ST. N.E.



SIGNED John E. Hunter
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE IRVINGTON AVE.
24-48

REMARKS: Tapped in to Main.

Nº 5166

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/21 1948

RECEIVED OF E. Hastetter

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Irvin Road

TO TAP San

SEWER, ON THE E.

SIDE

OF 9th St. E

AVE., TYPE OF STREET City

THE PREMISES BEING LOT NO. Pl 7512

HOUSE NO. 966

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.