## Nº 5169

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-2-48	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 330	DISTANCE FROM FIRST MANHOLE UP	/.3 '	7 Dees
WAS LATERAL AT CURB?	CURB LINE AND DEPTH		8 2 7
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Remley	
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERV	ED.	
X <	2 Found	ation not	started.
	o'Deep - 8'		e e e e e e e e e e e e e e e e e e e
	7 Deep	F F	Lline
· PROMOTER AND AN AND AND AND AND AND AND AND AND	7'Deep - 3/5 VAPT	DVOX. F. CUP	b Line in 26th SE
		Main Sewer	14 20 - 3 L
SIGNED R.J. Jungle	_ /3	ER'S OFFICE	
INSPECTOR HOR C	ITY Sold the self-transfer		
REMARKS:		the second of the second of the second of the second of	<del></del>

## Nº 5169

## PERMIT TO TAP SEWER

	Massillon, Ohio,	0/2	1948
RECEIVED OF	Provleto	FEE OF :	<u>\$2°~</u>
OR WHICH PERMISSION IS GRANTE	R Brown	. ·	
OTAP Sanctary	SEWER, ON THE	last	SIDE
26+14/	12. AVE. TYPE OF STREET	vila	
HE PREMISES BEING LOT NO.	927 House No.	330	ing the second s
	E WITH ORDINANCE NO. 2323. DULY P		Y COUNCIL, AND

D.: R. P. L.

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.