

N^o 5170

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3
11
1

DATE INSPECTED 8-5-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE UP STREAM 17' 10' Deep.

HOUSE NO. 1328


SIZE OF PIPE USED 6" up DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 7' 9'-6" Deep

WAS LATERAL AT CURB? See note

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N. ←



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: Lateral was to curb but was dug up & relaid to Main to get greater depth for basement.

Nº 5170

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO.

1948

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

SIDE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.