Nº 5172

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-4-48	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 222	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DEMM STREAM TO DITCH AT CURB LINE AND DEPTH	115 7' Deep.
WAS LATERAL AT CURB? YCS		Aston
WAS ATTACHED TO MAIN	The state of the s	
SHOW BY DIAGRAM RELATION OF LAT		
N <	-g' Found	dation not started.
6' D	cep 57.	
	5 × 7 Dec	Approx. E. Curb Line Main Sewer in 19th St
	1~,	& Main Sewer in 19 +2 St
	1/5'	
SIGNED R. J. MAPECTOR HOR CIT	FILED AT ENGINEER'S	s office & 1
INSPECTOR FOR CIT	Y	
REMARKS:		The second secon

Nº 5172

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohio,	2 00
RECEIVED OF	a.E. meal	FEE OF \$
TO TAP Sanitary	SEWER, ON THE	side
of 19th Mnd	AVE. TYPE OF STREET	int
THE PREMISES BEING LOT NO. 91	55 , HOUSE NO. 2	2.2
	ITH ORDINANCE NO. 2323. DULY PASSED BY	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR / Asler

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.