

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 18.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 18' 3' deep


WAS LATERAL AT CURB?_____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Demley,

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1ST ST. N.E.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 8-19-45

REMARKS:

Nº 5174

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO. 8/13 1948
RECEIVED OF L. C. Reynolds FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED L. C. Reynolds
TO TAP Sanitary SEWER, ON THE East SIDE
OF 1st Ave E AVE., TYPE OF STREET paved
THE PREMISES BEING LOT NO. DL 161 HOUSE NO. 1062

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.