

14
37
✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 5181

DATE INSPECTED 7-12-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 118'

HOUSE NO. 1834

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

12TH ST. SE.

← N.



SIGNED John E. Evers
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 8-27-48 Doc

REMARKS: _____

Nº 5181

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/19 1948

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED E. D. Taylor

TO TAP San

SEWER, ON THE E

SIDE

OF 12th SE

AVE., TYPE OF STREET driv

THE PREMISES BEING LOT NO. 53 (Pittsboro City limits)

HOUSE NO. 1834

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.