## Nº 5184

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-16-48	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	30'	12%
HOUSE NO. 1827			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?		n /	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Bemley	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING	SERVED.	
12 74 37.	5 120	. ·	
reconnection successive successiv		7'deg 18	30
SIGNED INSPECTOR FOR CITY	FILED AT EN	GINEER'S OFFICE	-27-43 Dec
PEMARKS.			

## Nº 5184

## PERMIT TO TAP SEWER

MASSILI	LON, OHIO, 8/19 1948
RECEIVED OF Rembey	FEE OF \$2
FOR WHICH PERMISSION IS GRANTED W. A.	muck
TO TAP SEWER, ON THE	SIDE
OF AVE. TYPE OF STE	BEET dest
THE PREMISES BEING LOT NO 37 Willy Signite	., HOUSE NO. 1827
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 23	323. DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR A. Kemley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.