Nº 5201

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-18-48	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 854			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	6° desh	
WAS LATERAL AT CURB? Yes	· · · · · · · · · · · · · · · · · · ·		
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR ASTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
WEBB, A			
7	1 - 4 deg/		
	y the		
,	C14 8/22 246	in the construction and all the three sections	
·			
		мд.	
SIGNED John Correll.	FILED AT ENGINEER'S OFFICE 9-24	-49	
INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE		
REMARKS:	na na manana da da manana m Tangan manana manan		

Nº 5201

PERMIT TO TAP SEWER

	MASSILLON, OHIO, 1948
RECEIVED OF M. aston	FEE OF ST
to	1 Water
FOR WHICH PERMISSION IS GRANTED	2 - Carlotte and C
TO TAPSEWEF	R, ON THESIDE
OF We had DW AVE. TYP	PE OF STREET Used
THE PREMISES BEING LOT NO. 3236	House No. 852
THE PREMISES BEING COTTO	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR It actor

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.