

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

13
51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE ~~TO~~ STREAM

123

10' deep

uh

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB?_____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Pemley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

15TH ST. N.W.



SIGNED

John E. Carter
INSPECTOR FOR CITY

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-16-43

REMARKS:

Tapped to main line

Nº 5205

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/27 1948
RECEIVED OF E. F. Heckendorn FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED E. F. Heckendorn
TO TAP Sanitary SEWER, ON THE South SIDE
OF Lin May Rd AVE., TYPE OF STREET Paved
THE PREMISES BEING LOT No. 8641 HOUSE No. 327-15th St.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Ramsey

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.