

Nº 5207

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-28-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 221

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

134' 4' Deep.


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

End of existing lateral found 3' out in pavement from curb.

Nº 5207

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/13

1948

RECEIVED OF A. J. Deana

FEE OF 2.00

FOR WHICH PERMISSION IS GRANTED A. J. Rogers

TO TAP San.

SEWER, ON THE N.

SIDE

OF Estle NE

AVE.,
ST.,

TYPE OF STREET Acid

THE PREMISES BEING LOT NO. 7683

HOUSE NO. 221

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Deana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.