

Nº 5208

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

11
16
✓

DATE INSPECTED 12-9-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM See sketch

HOUSE NO. 118

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Tapped

NAME OF CONTRACTOR Remley.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N ←

Main Trunk
Sewer in City
Hall Park



Side Walk - N. Side of
Tremont St. S.E.

Side Walk - E. Side 1st St. S.E.

SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-13-48

REMARKS: Tapping hub used to connect lateral to main
Trunk Sewer in City Hall Park.

Nº 5208

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/13 194

RECEIVED OF Geo Paris

FEE OF 2.00

FOR WHICH PERMISSION IS GRANTED same.

TO TAP San

SEWER, ON THE W.

SIDE

OF Tremont St

AVE.,
ST.,

TYPE OF STREET Paved

THE PREMISES BEING LOT No. 1122

HOUSE No. 118

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Rennley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.