

9-23

Nº 5211

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-8-48 IF SO HOW AND LOCATION FROM
FIRST MANHOLE up STREAM 6' 9' deep

HOUSE NO. _____



SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

23RD ST N.W. EXT.



SIGNED John Chamber
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-30-48 1st stream

REMARKS: _____

Nº 5211

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

1942

RECEIVED OF

FEE OF

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

SIDE

OF

AVE.,

TYPE OF STREET

THE PREMISES BEING LOT No.

11998

HOUSE No.

602

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.