

2-55

Nº 5225

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-19-48IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 716SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH109' W. Curb on 6TH ST. S.W.



WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SPRUCE AVE. S.W.

SIGNED

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 11-20-48

REMARKS: _____

Nº 5225

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/16 194

RECEIVED OF Byron Heltz

FEE OF 2.00

FOR WHICH PERMISSION IS GRANTED Same

TO TAP San

SEWER, ON THE N.

SIDE

OF Spruce St.

AVE.
ST.

TYPE OF STREET

Alled

THE PREMISES BEING LOT NO. 3312

HOUSE NO. 716

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bernard

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.