## Nº 5244

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1-6-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	•
HOUSE NO.	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	CURB LINE AND DEPTH 570 RM	SEWER
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Bemity	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED	, we will the second se
ERIE ST		
	N V	2 0
THE CONTRACT OF THE CONTRACT O		and the second and th
Mary Laboratory		
	et and an analysis and an anal	44.8
		4.5
	worder against control of the contro	<del>na namanana a ana ana ana ana ana ana an</del>
	<u>ERIE.</u>	St
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFIC	E +60 11342
REMARKS:	الاس <u>، المشاه بالمناف أنه أنه المناف المناف والمناف بالمناف بالمناف المناف المناف المناف المناف المناف المناف المناف</u> 	

## Nº 5244

## PERMIT TO TAP SEWER

	· Had	d
	MASSILLON, OHIO, JOS	19 <i>4</i>
	į.	ونمسيكي وس
- A Noon Wall	FEE OF \$	<
RECEIVED OF	FEE OF \$	
in the second	The Car	
FOR WHICH PERMISSION IS GRANTED	And the second of the second o	
1+	(N)	
TO TAPSEWER	, ON THE	SIDE
Esia	Paris	
OF AVE., TYP	E OF STREET & COLOR	
	, House No/ <u>/</u> /3	·
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E No. 2323, DULY PASSED BY THE CITY	Council, And
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		a de la companya de
Rama	7	
NAME OF CONTRACTOR	1	

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.