

Nº 5250

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-25-48

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1319

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Providence Ave N.E.



SIGNED

John Chamber
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

3-30-49 Doc

REMARKS: _____

Nº 5250

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/9 1949
RECEIVED OF Raymond Bernley FEE OF \$ 2.05
FOR WHICH PERMISSION IS GRANTED H. I. Jaggar
TO TAP San SEWER, ON THE S SIDE
OF Providence NE AVE., TYPE OF STREET Parad.
ST.,
THE PREMISES BEING LOT NO. 8766, HOUSE NO. 1319

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bernley

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.