Nº 5268

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-5-49	IF SO HOW AND LOCATION FROM 151 14 dec/1
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Diana
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
Lincoln Wa	Y L
The second section of the second section of the second section of the second section s	3
	10.6
	14:10
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 5-12-49
	nain

Nº 5268

PERMIT TO TAP SEWER

A A A A	/ Massillon, Ohio	4/27	194/
RECEIVED OF	1 hamen		
FOR WHICH PERMISSION IS GRANTED	from the	Il ch	- :
TO TAP Santan	SEWER, ON THE	south	SIDE
or in color Hay	AVE TYPE OF STREET	100 mand 11	
$m{V}_{i}$	7) f House N	915	
THE PREMISES BEING LOT NO	, HOUSE I	10	

Work to be done in accordance with Ordinance No. 2323. DULY Passed by the City Council, and

NAME OF CONTRACTOR (A.) . Unamu

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.