Nº 5272

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-5-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	11'	6 deals	4
WAS LATERAL AT CURB? 1 45		.		
WAS ATTACHED TO MAIN VCS	NAME OF CONTRACTOR	Dian	as	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
1174 57,	N.E.			6
			(**	15 deg
<u> </u>			6'ded of	
	4	,	× /	
			11. 3/39	
				*
2		-0	against ong confirmatible committee in a continue	A CONTRACT SERVICES CONTRACTOR
		See Supplement Section 1 - Section 1	ng ang minang mengganggan menggang at ang ang ang menggang menggang menggang menggang menggang menggang mengga Tanggang	ann a' ann an an an am aite an an Airean
SIGNED INSPECTOR FOR CITY	FILED AT EN	GINEER'S O	FFICE 5-12-49	<u> </u>
and the same of th	•			
REMARKS:			The strict was a second and the strict with the strict was a second and the strict with the strict was a second and the strict was a second an	

Nº 5272

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	5/- 4
Massillon, Ohio,	
	~ 00
RECEIVED OF Comer U. 1091	FEE OF \$2
At Elme	O. Vact
FOR WHICH PERMISSION IS GRANTED	- 10 g
TO TAP SEWER, ON THE	west_side
12/1/28	10 mld
ST.,	
THE PREMISES BEING LOT NO. 1396-8397 HOUSE NO.	1525
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323. DULY PA	SSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
al Maana	
NAME OF CONTRACTOR	

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.