

7-51

N^o 5275


FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-19-49IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 1025SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____8' DeepWAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Foundation not
started

SIGNED

R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5-20-1949

REMARKS: _____

Nº 5275

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/19 194

RECEIVED OF H. Astor

FEE OF 2.00

FOR WHICH PERMISSION IS GRANTED Herbert Carroll

TO TAP San

SEWER, ON THE W

SIDE

OF Johnson St. E.

AVE., TYPE OF STREET

ST., Alled

THE PREMISES BEING LOT NO. 8233

HOUSE NO. 1025

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Astor

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.