Nº 5287

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 6-21-49 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | • |
|----------------------------------|--|--|
| HOUSE NO. 1903 | | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH | great |
| WAS LATERAL AT CURB? Yes | | |
| WAS ATTACHED TO MAIN YES | NAME OF CONTRACTOR DIATA | |
| SHOW BY DIAGRAM RELATION OF LATE | ERAL TO WALL OF BUILDING SERVED. | |
| Main Ave | | 4 |
| | | 1 Tridegy |
| | | ~// |
| | 145 | 84 /8 |
| _ | A STATE OF THE STA | A STATE OF THE PROPERTY OF THE DESCRIPTION OF THE PROPERTY OF |
| to the second | | Separate and the second |
| SIGNED OF LAND | FILED AT ENGINEER'S OFFIC | 7-5-49 |
| INSPECTOR FOR CITY | | 4/2,000 |
| REMARKS: | • | 1000 |

Nº 5287

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | Massillon, Ohio,_ | 6/13 | 1949 |
|--|----------------------|---------------------|-------------|
| GQMi | Com to | |) 00: |
| FOR WHICH PERMISSION IS GRANTED | n Man | aforti | **** |
| do to | ER, ON TH E | south | SIDE |
| A Company | YPE OF STREET | oila | |
| THE PREMISES BEING LOT NO. PTOZZ | 59 House No | 1903 | |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINAL | NCE NO. 2323. DULY F | ASSED BY THE CITY C | OUNCIL, AND |
| RULES OF THE DEPARTMENT OF PUBLIC SERVICE. | * | • | |
| NAME OF CONTRACTOR | ma | | |

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.