

Nº 5296

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

7
48

DATE INSPECTED 7-28-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2614

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


2' 7' Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-28-49

REMARKS: _____

Nº 5296

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/15 1949

RECEIVED OF L. H. Smart

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Ronald Woods

TO TAP San

SEWER, ON THE N.

SIDE

OF Rhode Island St.

AVE.
ST.

TYPE OF STREET

Alley

THE PREMISES BEING LOT NO. 4507

HOUSE NO. 2614

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Smart

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.