Nº 5297

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

8
7
· Property

DATE INSPECTED 8-1-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7. Leep
WAS LATERAL AT CURB? YES	and the second s	
WAS ATTACHED TO MAIN 765	NAME OF CONTRACTOR Albreght	
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
VERMONT. A	NVE S.E.	3
		1 7 des
	50	2 780%
1 1 91	Commence Assessed reservations and	ennergy and order to the state of the state
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 8-1	7-47
REMARKS:		

Nº 5297

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohio,	7/33	_1949_
RECEIVED OF	for in	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED			
TO TAP SE	EWER, ON THE	7	SIDE
or Ave	TYPE OF STREET	a Comment	
THE PREMISES BEING LOT NO.	, House No.	1956	····
WORK TO BE DONE IN ACCORDANCE WITH ORDIN	IANCE No. 2323, DULY PA	SSED BY THE CITY CO	UNCIL, AND
Elila.	a DL		
Name of Contractor	1		

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.